



























A*1 		B*1 	
C*1 	D*1 	E*2 	
		F*2 	
		G*1 	
H*1 		I*1 	
J*2 	K*1 	L*2 	S*4 
M*2 	N*2 	O*2 	P*2 
R*2 	Q*2 		
U1  M3.5*40 =12PCS	U2  M3.5*30 =8PCS	U3  M3.5*25 =14PCS	U4  M3*20 =8PCS
U5  M3*16 =12PCS			

P1



U2 M3.5*30=4PCS


U4 M3*20=8PCS



U1 M3.5*40=6PCS


U3 M3.5*25=4PCS

P2




U1 M3.5*40=6PCS

U2 M3.5*30=4PCS



M3*16=12PCS



M3.5*25=10PCS