







J/K1(X1)




A(X2)




B(X2)




G/A(X2)




D1(X1)




C(X2)




(X6)



M(X2)




P(X1)




(X60)


1




B(X2)




(X2)




(X20)




2




A(X2)







(X2)




(X20)




3	 G/A(X2)	 (X2)	 (X20)
--------------	--	--	--




4	 M(X1)
--------------	---




5



6




M(X1)




7


CLICK




8




D1(X1)




9




P(X1)




10




J/K1(X1)



11



C(X2)



12

